

SIMON'S SPORT SHOP

2840 HIGHWAY 10

MOUNDS VIEW, MN 55112

784-2888 • FFL#41-5036

DEPARTMENT OR REQ. NO. 90179

PURCHASE ORDER

TO

SHIP TO

Remington Arms Co.
14 Hoefler Ave
XXXX Ilion, NY 13357
ATTN: Jack Kast

DATE OF ORDER	11-25-94	DATE REQUIRED		SHIP VIA		FOB	
TERMS		QUOTATION NUMBER		FOR RESALE <input type="checkbox"/>		FOR USE <input type="checkbox"/>	
QUANTITY		PLEASE SUPPLY ITEMS LISTED BELOW				UNIT	PRICE
ORDERED	RECEIVED						
1		Remington 700 BDL 7mm mag. Ser#369743					
2							
3		Owner's complaint - fires on closing					
4		His letter accompanies					
5							
6							
7							
8							

IMPORTANT OUR ORDER NUMBER MUST APPEAR ON INVOICES, PACKAGES & CORRESPONDENCE
ACKNOWLEDGE IF UNABLE TO DELIVER BY DATE REQUIRED

BY

ue *ST Simon*

seated another round from the magazine. The rifle fired almost immediately as I placed the bolt in the down position. I had not moved my hand near the trigger at this time.

After the initial shock, I again examined the rifle and could see nothing wrong. I repeated the procedure by ejecting the spent round and placing the last round from the magazine into the chamber. I cautiously placed the bolt in the down position and very shortly afterwards (< 1 second) the rifle again fired. At the time of the incident, the temperature was in the upper 30°F range, it was windy, and it was misting or lightly raining.