

TELEPHONE (904) 438-3019

3019

DATE 9-2-94

TO Remington Service Division  
14 Hoefler Avenue  
Ilion, New York 13357

SUBJECT Model 700 Remington  
.270 S. N. 86706785

As I told Colleen by telephone, my Model 700 did misfire while on a hunting trip. It had not done so during my "zeroing in" before leaving home. On two occasions it did fire upon my pushing the safety forward. Please check it over and let me know what has to be done to make it safe to use again. Also please send me an owners manual.

SIGNED

Horace Lemper

PS05769