

Model 700
280 cal.
Serial # A6817421

Arthur R. Shafer
5710 West "A" St.
West Linn, OR 97068

Remington Arms.

3/28/94

Mr. & Mrs. A.R. Shafer
5710 West "A" St.
West Linn, OR 97068

Two years ago this Model 700 280 caliber rifle discharged by its self upon release of the safety. The rifle was in the gun rack in our pick-up when this accident occurred. The bullet went through the side of the cab of the pick up, then struck the camper jack, then at that point hit the hat on a man's head. While ~~he was~~ walking across the parking lot back to his own pick up.

I have owned this weapon for about 15 years. This has never happened before or since. We took the rifle to a reputable gun smith, neither he nor I could make it discharge on its own again.

Until we saw 60 min. on T.V. we thought it was just flunk accident. Please repair or replace as soon as possible.

Thank you,
1-503-656-7439