

REPAIR Y/N UPDATE FUNCTION: I INTEXT (F)ASV (U)PDATE (I) NO E (ACT) 05/12/94
ENTER REPAIR NUMBER ----- 9415077 06 57 10
SERIAL NO: 5500005 NEW SERIAL NO: LABEL: TUN
FROM: COLT GUN REPAIR SMITHGEORG 3A CAL: 12-150
SNI GEORGE J. TYPE: BDL PAR
DELT 4. 10 94. ADDRESS/ED: M-STUDS

REF: 05 19668
SHIPPED TO:

DATE CODES: 05 12-71
OTHER (0000000000)
L REAF EIGHT

CONSENTS: CALL TAG ATTN: TOM NAGLE

DATES:		TO	FROM	
RECEIVED	05 05 94	GALLERY	05 10 94	05 10 94 ENTERED BY: FPS
LOANED	05 15 94	PROD SERV	00 00 00	05 09 94 REPAIRMAN: RBS
ESTIMATED	00 00 00	TAG GUNS	00 00	TYPEST:
PROMISED	00 10 10	REJECTED	00 00	CORRESPONDENT:
PAID AHEAD	00 00 00	CASH RECEIVED:	\$ 0.00	BILL TYPE: D
SHIPPED	05 17 94			
WILL TAKE COD PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CLST MAINT				

REPAIR NUMBER: 9415077 CHARGE (AWAIT RESP) COD PRINTED 05/12/94
CUSTOMER NAME: SMITH, GEORGE J. 06 58 04

REQUEST: GUN FIRES SOMETIMES WHEN PUSHING SAFETY OFF, READ LETTER.
MAIN FAULT: UPON RECEIPT, WE WERE UNABLE TO DUPLICATE THE CUSTOMERS
CONCERN. EXAMINATION REVEALED THAT THE GEAR ENGAGEMENT HAS
BEEN RESET & RESEALED OUTSIDE THE FACTORY. THE SEALANT IS
MISSING FROM THE OVERTRAVEL SCREW & THE TRIG ADJ. SCREW.
THERE IS NO OVERTRAVEL PRESENT IN TRIG. DATE OF MFG: 12-71

PARTS:	\$	30.50	1	26345 TRIGGER ASSEM RH
	\$	0.00	19900005	TEST
LABOR:	\$	0.00	REPLACE COMPLETE TRIGGER ASSY. AT 1/2 NORMAL REPLACEMENT	
	\$	0.00	COST, AS GESTURE OF GOODWILL -	
	\$	0.00	RBS/HAR	

REPAIRMAN'S INITS: RBS NUM OF WFS: 04 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 40.81 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR