

Gear Lift .0075

Trig Bull 4.5 lbs

Gear engagement has been re-set
and re-sealed outside of factory.

Sealant is missing from overtravel
screw and Trig adjusting screw.

There is no overtravel present in
Trig.