

Repair Order Number



Repair Order Number RE00072706	Description/Serial Number 6238723	Repairman - Dale Lewis Date Received - 11/20/2003
Account # - R-	Model 700 Center Fire Caliber: 22250 BDL	Estimate Date - 11/13/2003 Current Date - 11/25/2003
Customer NIKKI STOUT 73485 HWY 64 MEEKER, CO 81641 US	Return To NIKKI STOUT 73485 HWY 64 MEEKER, CO 81641 US	
Phone (H) (970)-878-6062 XW Phone (W) (970)-878-3297	Fax Email	

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M125	STOCK CRACKED		
M992	FIRES WHEN TAKEN OFF SAFE		
M993	LACK OF PACKING CRACKED		

Material #		MaterialDesc	Repair	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000119		GR-TEST		1	1	0	Y
4000294		GR-CHECK TPA		1	1	0	Y
Service Total:				22	22	0	

ProblemNotes	customers stock broke when received(2 1/2" piece split from toe) ...will replace w/ good slave from bench will be updated style...action and trig assem dirty,adjustment screws reset,poor maintenance...clean action,replace trig assem \$20 per prod service				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date