

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product Service*ORDER
R 95-04908INITIAL
JJMCUSTOMER ORDER NO
Y24553DATE RECEIVED
01/25/95DATE OPENED
02/08/95DATE CODE
BM 1-92SERIAL NUMBER
C6695401

NEW SERIAL NUMBER

MODEL AND GRADE
700 22-250

ADL

ACCESSORIES

W/STUDS

FROM:

SPORTS WORLD
5800 S. LEWIS SUITE 154
TULSA

OK 74105

SHIP TO:

SPORTS WORLD
5800 S. LEWIS SUITE 154
TULSA

OK

74105

CUST NO:005259 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

3-27

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Rust found on bolt body

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00
8.00
28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			F1	
BOLT ASSY.		B3			F2	
BARREL ASSY.		B4		D1	F3	
REC. ASSY.		B5		D2	F4	
WOOD			C1	D3	F5	
METAL			C2			

MAIN FAULT

Upon receipt we could not cause rifle to fire on its own. We did find the trigger disengaged & stop screws were bad the screws removed, indicating the adjustment screw been in - out. The action was in good working.

PARTS

#26345

COMMENTS

Replace the original trigger assembly and clean the action at 1/2 the normal repair cost, as order of good will

Jo. Chaud

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS05820