

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 95-25607INITIAL
FPSCUSTOMER ORDER NO
17466

W/I SPENT CASE

Product Ser.

DATE RECEIVED
10/13/95DATE OPENED
10/16/95DATE CODE
CC 4-82SERIAL NUMBER
B63B4035

NEW SERIAL NUMBER

MODEL AND GRADE

700 270 WIN BDL

ACCESSORIES

SCOPE BASE

L/SIGHTS

W/STUDS

FROM:

SPORTSTER INC, THE
C/O NBS
4542 S BROADWAY
TYLER

TX 75703

SHIP TO:

SPORTSTER INC, THE
C/O NBS
4542 S BROADWAY
TYLERTX
75703

CUST NO: 033205 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

11/15/95 UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE *20.00*
EXCISE
TAX
INSURANCE
UPS *8.00*
PARCEL POST
TOTAL *28.00*

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2		E1	F1	
BOLT ASSY		B3		E2	F2	
BARREL ASSY.		B4		E3	F3	
REC. ASSY.			D1	E4	F4	
WOOD			D2	E5	F5	
METAL			C1	D3		
			C2			

MAIN FAULT

Rifle mfg 1982 upon receipt, the rifle is in operation. The trigger will not reset, and the firing pin follows down when closing the bolt. Examination revealed that all 3 trigger adjustments screws have been set and a Green colored lubricant is applied.

PARTS

COMMENTS

See left only .003 below min. spec
26345
Replace the compact trigger assembly & clean action at 1/2 round upon test
Check shoulder & position

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>hve</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/94

PS05825