

RECEIVING AND ESTIMATING REPORT

COMMENTS

1STK & BDL NOT OUR MFG

INITIAL
FPS

CUSTOMER ORDER NO
068182

DATE RECEIVED
01/16/91

DATE OPENED
01/24/91

DATE CODE

SERIAL NUMBER
B6879036

MODEL AND GRADE
700 458 WIN MAG

ORDER
R 91-02440

ACCESSORIES
SCOPE BASE W/STUDS

FROM:

SPORT CENTER
211 E CRYSTAL AVE
LAKE WALES

FL 33853

SHIP TO:

SPORT CENTER
211 E CRYSTAL AVE
LAKE WALES

FL
33853

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

1) *gun action* 2) *action feed from magazine*

MAIN FAULT

1) *gun action complaint because trigger assembly has been improperly adjusted out of factory (evidenced by red color sealant) insufficient rear engagement. Trigger pull min. spec. 3 pounds. 2) This action was originally a different Remington caliber, ~~originally~~ apparently of the feed-rail cut won't handle the 458 Win Mag caliber.*

PARTS

1) *Send quotation for new trigger assembly at 1/2 formal cost, as gesture of good-will*

2) *We cannot modify the feed rails*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 7/90

PS05855