

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-09812

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/06/92

04/13/92

OV 7-79

A6791557

700

30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

ST LAURENT, DAVID
585 KEELING RD
NORTH POLE

AK 99705

ST LAURENT, DAVID
585 KEELING RD
NORTH POLEAK
99705

CUST NO: 060810 C-10.1

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

D1

REC. ASSY.

B5

D2

WOOD

C1

D3

METAL

C2

E2

E3

E4

E5

F2

F3

F4

F5

MAIN FAULT

Cannot duplicate Complaint - Trigger assembly and safe operate properly. Possibly or safe showed trigger assembly in open bolted outside of factory & trigger pull adjustment has changed (replant removed) trigger pull below old spec. measure at 3 pounds.

Trigger pull 3 pounds; acc - lift .009"

PARTS

COMMENTS

Offer to re-adjust present trigger to specification. If we can install a new trigger assembly at a normal cost as a gesture of good-will if that will better restore confidence in the safe.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

G06035 05/1/92

PS05902