

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R 91-27118	
INITIAL JJM		CUSTOMER ORDER NO.		BBL HAS BEEN CUT OFF			
DATE RECEIVED 12/19/91	DATE OPENED 12/30/91	DATE CODE RI 11-76	SERIAL NUMBER A6382712	NEW SERIAL NUMBER	MODEL AND GRADE 700 22-250		BDL
ACCESSORIES		W/STUDS		SCOPE BASE		L/SIGHTS	
FROM:				SHIP TO:			
SOUTH WEST GUNS 107 S RICE BOX 432 HAMILTON USA				SOUTH WEST GUNS 107 S RICE BOX 432 HAMILTON USA			
				TX 76531		TX 76531	
CUST NO: 016102 C.D.D.L							
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 1-14-92
							VIA UPS
GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE							REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP							
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT <i>Trigger assembly has been irregularly adjusted outside factory. Over travel is greatly excessive - adjustment screws for no effect. Trigger movement somewhat sluggish &amp; bolt release stroke appears to be gummy. Lubrication needed.</i>							
<i>Trigger pull 3.8 pounds; rear lift 100.7"</i>							
PARTS				COMMENTS			
				<i>Install new trigger assembly and change to normal cost, as getting good with.</i>			
REPAIRMAN		PROOF		CLEAN		TEST	
DE							
GALLERY TESTER		DATE		DATE		DATE	