

Serial
Number:

6355976

Model: 700



RE00050895

5412 Westridge Road
Anaheim, CA 92807
August 9, 2002

Remington
Ilion Plant & Custom Shop
14 Hoefler Avenue
Ilion, NY 13357

*Date Code
WT 8/70*

Customer Service:

Re: Model 700, Safety Modification Program

Upon reading of the mod program, I called 877-387-6691 and confirmed that my rifle is eligible for the retrofit.

The Remington Repair Form is enclosed with the requested information.

The charge for this rework can be placed on my Visa account 4128002078221137, exp. 3/05.

Thank you for your help. This firearm did discharge accidentally during unloading – first time about 20 years ago and last fall.

Thank you for your assistance.

Sincerely,

Tom Townley

Tom Townley
(714) 998-2810

Enclosure:

Remington Repair Form

*8/19/02
Action duty
all 3 adj screws attached
Clean action &
replace trigger assembly 20.00
Post*