

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER
R 98-16201

INITIAL
JJM

CUSTOMER ORDER NO
660390

DATE RECEIVED
08/12/98

DATE OPENED
08/13/98

DATE CODE
LF 2-85

SERIAL NUMBER
7643992

NEW SERIAL NUMBER

MODEL AND GRADE
7 223

ACCESSORIES

W/STUDS

FROM:

TANNERS GUN REPAIR SERVICE
251 SOUTH LEE STREET
LABELLE FL 33935

SHIP TO:

TANNERS GUN REPAIR SERVICE
251 SOUTH LEE STREET
LABELLE FL 33935

CUST NO: 065593 C.O.D.L.

ACCOUNT NUMBER

2293001

ACCOUNT NUMBER N/C

WRITE

☐

PROM DATE

ESTIMATED

8-18

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

28.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

36.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	E				
TRIGGER GROUP		B1		E1	F1	
BOLT ASSY.		B3		E2	F2	
BARREL ASSY.		B4		E3	F3	
REC. ASSY				E4	F4	
WOOD				E5	F5	
METAL						
MAIN FAULT						

Trigger gun fails when cocking the bolt or jiggling the bolt when the rifle is on the fire position. Check to see if bolt is cocked

Upon receipt the rifle could not be moved to the safe position once on fire. We found the safe bent & binding, and the inner of the trigger group dirty. Appears to be gun inclusion opening on the bolt body.

COMMENTS

*Replace the complete trigger group & Bolt assembly
No charge for bolt
1/2 for complete trigger group*

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
302					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 7/97

PS05991