

ATTACH
TO GUNJOB
NO. 660390

PRICE

852502

REPAIR #

Date Left 10-23-97 Date Promised _____Make REMINGTON Model 7Ser. # 7643992 Cal./Ga. .223Owner TOMMY MCGILLAddress P.O. Box 276City FELDA State FLAZip 33930 Phone 675-1719

- ☒ Malfunction ☐ Broken Pts. ☐ Reblue
☐ Rebarrel ☐ Action Work ☐ Clean
☐ Scope Mounts ☐ Recoil Pad ☐ Refinish
☐ Other _____

☐ Sent To _____Details FIRING PIN MALFUNCTION?RETURN TO REMINGTON!IN THE BOLT BODY.RECOMMEND RETURN TO REMINGTON
for factory repairs.

APPROX. DELIVERY DATE CAUTION!!
 COMMENTS: DO NOT ATTEMPT TO
USE THIS FIREARM PRIOR TO
COMPLETION OF FACTORY REPAIRS.
IT COULD FIRE WITHOUT WARNING
WHEN IN THE "FIRE" POSITION.
EXTREMELY DANGEROUS!!

EQUIPMENT RECEIVED WITH REPAIR JOB:

- ☐ SCOPE ☐ LENS COVER ☐ SLING ☐ OTHER
☐ CASE ☐ CUSTOMER'S AMMO (____ ROUNDS)

078-190-358 R296

White Copy - Keep

Pink Copy - To Customer

Buff Tag - To Gun

REORDER THIS
FORM FROM:**BROWNELL, Inc.**200 SOUTH FRONT STREET
MONTEZUMA IA 50171-1000
Phone: 515-623-5401 Fax: 515-623-3896100 Repair Invoices
#084-088-100500 Repair Invoices
#084-088-500

I HAVE RECOMMENDED THAT MR. MCGILL RETURN
 THE RIFLE TO REMINGTON FOR THE NECESSARY
 FACTORY REPAIRS

SERVICE
street
3935
113DATE PICKED UP/CUSTOMER INITIALS
P.M.HOME
PHONE 675-1719WORK
PHONESTATE FLA.33930
CAL/GAUGESERIAL #
7643992223SAFETYSEAR DOESFETY DOESFOUND A CRACKREMINGTONAL NO. 76439921997.REVEALED THAT THEPERLY ENGAGE,UPON COCKING.WHEN THE SAFETY ISFETY DOES NOTTO A CRACK IN THETO HAVE BEENAPPEARS TO HAVEAND USED VERY

DEAR REMINGTON,

MR. MCGILL BROUGHT HIS REMINGTON
MODEL SEVEN, .223 CAL., SERIAL NO. 7643992
TO ME FOR REPAIR ON OCT. 23, 1997.

MY INSPECTION OF THE RIFLE REVEALED THAT THE
FIRING PIN & SEAR DOES NOT PROPERLY ENGAGE,
CAUSING THE FIRING PIN TO FALL UPON COCKING OR
JIGGLING OF THE BOLT LEVER WHEN THE SAFETY IS
IN THE "FIRE" POSITION. THE SAFETY DOES NOT
FUNCTION PROPERLY. THERE IS ALSO A CRACK IN THE
BOLT BODY.

THE FIREARM DOES NOT APPEAR TO HAVE BEEN
ABUSED OR MISTREATED. IN FACT, IT APPEARS TO HAVE
BEEN TAKEN CARE OF VERY WELL AND USED VERY
LITTLE.

I HAVE RECOMMENDED THAT MR. MCGILL RETURN
THE RIFLE TO REMINGTON FOR THE NECESSARY
FACTORY REPAIRS.

SINCERELY,
GENE TANNER

TANNER'S GUN REPAIR SERVICE
251 South Lee Street
LaBelle, FL 33935
(941) 675-0413

NEW PARTS

OTHER WORK:
SCOPE & SIGHTING
ACTION WORK
STOCK WORK
GUN

ICE

852502

REPAIR #

TANNER'S GUN REPAIR SERVICE
251 South Lee Street
LaBelle, FL 33935
(941) 675-5413

der Pat McGill
P.O. Box 276
Felda, FL 33930

DATE IN 10-23-97	DATE FINISHED/NOTIFIED 10-25-97 ☒ CALLED ☐ MAILED	DATE PICKED UP/CUSTOMER INITIALS P.M.
NAME TOMMY MCGILL		HOME PHONE 675-1719
STREET P.O. Box 276		WORK PHONE
CITY FELDA	STATE FLA.	23930
MAKE REMINGTON	MODEL 7	SERIAL # 7643992
		CAL/GAUGE 223

SERVICE REQUIRED

CHECK/REPAIR FIRING PIN/SAFETY

FOUND THAT FIRING PIN & SEAR DOES NOT PROPERLY ENGAGE. SAFETY DOES NOT FUNCTION PROPERLY & FOUND A CRACK IN THE BOLT BODY.

RECOMMEND RETURN TO REMINGTON FOR FACTORY REPAIRS.

APPROX. DELIVERY DATE

CAUTION!!
COMMENTS: DO NOT ATTEMPT TO USE THIS FIREARM PRIOR TO COMPLETION OF FACTORY REPAIRS. IT COULD FIRE WITHOUT WARNING WHEN IN THE "FIRE" POSITION.

EXTREMELY DANGEROUS!!

EQUIPMENT RECEIVED WITH REPAIR JOB:

☐ SCOPE ☐ LENS COVER ☐ SLING ☐ OTHER
☐ CASE ☐ CUSTOMER'S AMMO (____ ROUNDS)

PARTS

TEST AMMO

TAX
TOTAL TAXABLELABOR
POSTAGE & INSURANCE

MISC. NON-TAXABLE

TOTAL NON-TAXABLE

TOTAL DUE

076-100 358 R296

White Copy - Keep

Pink Copy - To Customer

Buff Tag - To Gun

REORDER THIS FORM FROM:

BROWNELLS, Inc.

200 SOUTH FRONT STREET
MONTEZUMA IA 50171-1000
Phone: 515-623-3401 Fax: 515-623-3896

100 Repair Invoices
#084-088-100

500 Repair Invoices
#084-088-500

I HAVE RECOMMENDED THAT MR. MCGILL RETURN THE RIFLE TO REMINGTON FOR THE NECESSARY FACTORY REPAIRS.

Sincerely,
Gene Tanner

REMINGTON
CAL NO. 7643992
1997.
REVEALED THAT THE
DOES NOT PROPERLY ENGAGE,
UPON COCKING
WHEN THE SAFETY
SAFETY DOES NOT
A CRACK IN
TO HAVE BEEN
APPEARS TO
AND USED