Date: 17/16	104		
By: Bruce	NAVIS	SR	•

FIREARM INSPECTION WORKSHEET

BACKGROUND	
Customer name: T+ M Shooting SPS	
R.E. Number: § 9348	
Reason for inspection: FSP	
<u>FIREARM</u>	
Manufacturer: 10m Model: 700	
Serial Number: £6836926 Date of Manufacture:	7/95
Overall external condition: Good	
Barrel condition: O/CAY	
Receiver condition: OKAY	
Stock condition: OKAY	
Bolt/firing pin condition: Olay	
Trigger assembly condition:	
Engagement:	
Adjustments/alterations	
Other: Trig - Rusted	
Headspace:	
Function evaluation:	-

Feeding:
Extraction/ejection:
Trigger pull: 7#
Manual safety: OCAY
Test firing results (if applicable):
DISPOSITION
could not diplicate concern. Trig. very Rusty+
Could not duplicate CONCERN. Triq. Wery RUSTY+ BINDING. Rephace TVA & CLEAN Action At 1/2 MSP
ADDITIONAL COMMENTS
\\
\$. .