

REPAIR NUMBER: 9511378 NO CHARGE
CUSTOMER NAME: TEELE, GROVER C

EST/LETTER LSTD

06/13/95
15 13 38

=====

REQUEST: HAD TO USE BOTH THUMBS TO REMOVE SAFE FROM SAFE TO FIRE
POSITION GUN FIRED WHEN SAFE WENT TO FIRE POSITION.

MAIN FAULT: BBL. FAILS ATTRIBUTE TEST, NEW BBL. ISSUED,
SAFE OFF FORCE WAS HEAVIER THAN NORMAL AS REC'D. THE ONLY WAY
THAT THE GUN COULD BE MADE TO FIRE WAS WITH THE SAFE OFF AND
THE TRIGGER PULLED. - DATE OF NFG: 07-83

PARTS: \$ 0.00 1 92458 TRIGGER ASSEMBLY
\$ 0.00 19900005 TEST
\$ 0.00 19900004 CLEAN
\$ 0.00 1 34992 BARREL ASSEM COMP 243
\$ 0.00 19900003 PROOF
\$ 0.00 19900006 TARGET

LABOR: \$ 0.00 EXCHANGE TRIGGER ASSEMBLY AT NO CHARGE DUE TO
\$ 0.00 HARD OFF SAFE CONDITION.
\$ 0.00 TRIGGER PULL MEASURED 4 1/2 LBS.
\$ 0.00 POLISHED CHAMBER
\$ 0.00 NOTE: DID NOT NEED BOTH THUMBS TO TAKE SAFE OFF

REPAIRMAN'S INITS: RBS NUM OF WKS: 05 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR