

RECEIVED

DEC 12 1994

CONSUMER SERVICE

222 Five Point Dr.
Talbott, Tn. 37877
December 5, 1994

Service

Remington Arms Co.
1011 Centre Rd.
Wilmington, De. 19805

Dear Sir:

Some years ago I purchased new a Remington Mohawk 600,
caliber 308, Serial # A6574297.

I believe you had a recall on some Remington Model 600's
because they might fire when the safety was released. I
had no problem with mine. I tried several times, empty
of course, to see if I could cause such a misfire and
could not. I did not write to see if my rifle was included
in the recall as you suggested.

Recently after cleaning and lubricating my rifle, I noticed
that when I raised and lowered the bolt the firing pin went
forward as the bolt was closed. I put the safety on and
the firing pin stayed back as the bolt was closed. When I
pushed the safety off, the rifle fired (empty of course),

Please provide information as how to return this rifle to
you for correction.

Thank you.

Sincerely yours,

William R. Thomas

William R. Thomas