

# Remington

## Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: 376845
Name: Johnie L. Teague	Date of Purchase: 1972-used
Address (no PO Boxes):: 2232 Defoors Ferry Rd NW	
City: Atlanta	State: GA Zip: 30318
Phone (Daytime): 404 350-7884	Fax:
E-mail Address: JLTTEAGUE@MSN.COM	
Please describe your problem:	
Bolt Lock mechanism safety Modification program	
Also Gun occasionally fires when safety is moved to fire position	

*State  
Call  
ER  
10/68*

Serial Number:

# 376845

Model: 700



## RE00075181

brand, handload specifications, etc.)

# 75181

contact the repair center for services

YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A BAG WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

*1/14/04 Upon receipt we could not duplicate the reported fire when safety is moved to fire. Tray adj & stop screws have been checked out, some rust found on tray housing. Repair tray screws \$20.00 Quote*

<http://www.remington.com/support/repairsvc/repairform.htm>

12/19/2003