Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00075573

Account # - R-

Description/Serial Number

6848802

Model 700 Center Fire Caliber: 30-06

BDL

Repairman - Dale Lewis

Date Received · 1/14/2004

Estimate Date -

Current Date - 1/28/2004

Customer

4

THE TRADING STATION

618 STATE ST

AUGUSTA. KS 67010 US

Return To THE TRA

THE TRADING STATION

618 STATE ST

AUGUSTA. KS 67010 US

Phone (H)

(316)-775-0901

Fax

(316)-775-0198

Phone (W)

Email

Reported	Pro	ilems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FI
M992	FIRES WHEN TAKEN OFF SAFETY		

Material #	<u>MaterialDesc</u>	Quantity	<u>Quantity</u>	<u>Quantity</u>	<u>Warranty</u>
		Needed	From Inv	From Kit	(Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part	Total:	1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service	Total:	22	22	0	

ProblemNotes

upon receipt the trig was seized up the rifle fired when trig was pulled and the safe removed.trig engagement screws altered-trig components covered with sticky substance replace ta at \$20 per

product service

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date