

Gentlemen,

This letter is re a safety mechanism problem with your model 788 bolt-action rifle.

I own a model 788 cal. 308 winchester and there is definitely a problem, for it will fire when removed from the safe to fire position, without pulling the trigger. This was discovered today, luckily, with the absence of injury to others or myself.

While it is to my understanding that this model has been discontinued, it is not at all clear why, or if this specific problem has arisen before in this model. Also it is equally beyond my knowledge whether there has been a recall of the 788. If there has, then it is my fault for not recognizing ~~do~~. If not, then may I suggest that you all make an effort to do so before some calamity occurs. Write or call (404)-663-2452

resp.,

Joe D. Teel Jr.

P.O. Box 284
Pine Mtn., GA.

31822

RECEIVED

DEC 10 1990

J.A. STEKL

Joe D. Teel Jr.
P.O. Box 284
Pine mtng GA.

31822



Remington Arms Co.
Firearm Div.
Lonoke, AR
72036

urgent