

Date: 10/14/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: ERWIN TIPTON

R.E. Number: 101948

Reason for inspection: FSR

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: 6880777 Date of Manufacture: 6/75

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition: OKAY

Engagement: ALT FILED

Adjustments/alterations: ALT FILED

Other: —

Headspace: —

Function evaluation: —

Feeding: —

Extraction/ejection: —

Trigger pull: 2.5 lb

Manual safety: OKAY - BOLT LOCK

Test firing results (if applicable): —

DISPOSITION

TRIG. SET SCREWS ADJUSTED. COULD NOT DUPLICATE
CONCERN. REPLACE TPA UNDER BOLT LOCK PROGRAM

ADDITIONAL COMMENTS

RO R 8 20.00. Quote