bcc: Arms Service
R-90-02732

Remington. Hold for reply
J. Hutton & B. Ericson

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 15, 1990

Texas Gun Shop, Inc. 4518 S. Padre Island Dr. Corpus Christi, TX 78411

Gentlemen:

Examination has been completed on the Model 700 BDL 25-06 Rem. caliber rifle, serial number 6516178, that you returned to us a short time ago because, "trigger is defective. Rifle fires when safety is disengaged."

The returned firearm, which was produced in February of 1972, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the rifle appeared to be fair, and it was noted that scope mounts and a recoil boot has been added after it originally left our factory. In going over the individual parts, we found the headspace, chamber and recoil shoulders all to be normal. Trigger pull was found to be 4 pounds and the sear-lift with the safety in the "on-safe" position was also within specifications at .0105".

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. Many attempts were made to cause the rifle to fire when the safety was moved from the "safe" to the "fire" position, but it did not happen. The only way the rifle could be made to fire was with the safety in the "fire" position and the trigger pulled; it functioned normally and as designed.

Since we found the rifle to function properly in every respect, we are prepared to return it in its present condition. However, if our customer desires, we will replace the trigger assembly at nocharge as a gesture of good-will, if it will better restore confidence in the rifle (either option is subject to a \$10.00 handling plus the return shipping amount). We will await the decision and reply.

Thank you for affording us the opportunity to examine the firearm and report our findings.

Sincerely,

J.A. Stekl, Specialist

roduct Service

JAS: tpp