

# RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN: JIM SIEKL  
STAINLESS STEEL

W/2 SPENT CASES

INITIAL RLP	CUSTOMER ORDER NO.		DATE RECEIVED 02/15/90		DATE OPENED 02/20/90	DATE CODE WI 8-74	SERIAL NUMBER A6262194	MODEL AND GRADE 700	17	BDL	ORDER 90-06903
ACCESSORIES W/STUDS		SCOPE BASE								R	

FROM:

DALE TRUE  
RT 1  
LEROY KS 66856

SHIP TO:

DALE TRUE  
RT 1  
LEROY

KS  
66856

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPSD
----------------	--------------------	--------------------------------	------------	-----------	-------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☒ MARRED

CUSTOMER'S REQUEST

"The rifle fires when you release the safety with the barrel pointing down"

MAIN FAULT

Connector is broken from pierced primers - Remington factory ammo being used.

PARTS

1) replace trigger assembly at NO-charge  
2) Check firing pin hole in bolt face - replace bolt at NO charge, if necessary.  
3) Complete repairs and return, do not charge \$10.00 handling or return postage  
2/22/90  
JH.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS06106