

File Number:	20977		Arms Service number:	93247	
Last Name:	THRASHER		First Name:	ALLEN & CHERYL	
Street:	30375 211TH STREET		City:	EASTON	
State:	KS	Zip:	66020	Home Ph:	913-758-1125
Work Ph:		Product Type:	F	F A T O	
Type Concern:	PD	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM AND \$1,305.05		Settlement Amount:	\$1,305.05	
Date Opened Rem:	2/16/2005	Date Opened by P/S:	2/1/2005	Caliber:	243
Date of Incident:		Date Closed:	2/18/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	A6515480	Date Code:	
RAMAC:	700			Date Mfgd:	10/15/1977
Custody:		Litigation:	☐	PreLitigation:	☐
				Obsolete:	☐
Time of Modification:	8.13.56 AM	Comments:	Claims he was loading rifle as he left house, as he took safety off the rifle fired. Bullet went through garage, garage door causing damage. ARS label, box and letter sent 2/1/05. Could not duplicate concern - TA was rusty - the trigger did not reliably return under the sear. Clean action and install new TA - charge 230145. Repair and Shipping Document 2/24/05.		
Date of Modification:	2/2/2005				