

Repair Order Number



Repair Order Number

RE00093247

Description/Serial Number

A6515480

Repairman - Bruce Travis

Date Received - 2/21/2005

Account # - R-

Model 700 Center Fire Caliber: 243 BDL

Estimate Date -

Current Date - 2/22/2005

Customer

ALLEN THRASHER

30375 211ST ST

Return To

ALLEN THRASHER

30375 211ST ST

EASTON. KS 66020 US

EASTON. KS 66020 US

Phone (H) (913)-758-1125

Phone (W)

Fax

Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	GUN FIRED WHEN MOVING BOLT		

		Repair			
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	<u>1</u>	<u>1</u>	<u>0</u>	Y
Part Total:		<u>1</u>	<u>1</u>	<u>0</u>	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	<u>0</u>	<u>0</u>	<u>0</u>	Y
4000119	GR-TEST	<u>1</u>	<u>1</u>	<u>0</u>	Y
Service Total:		<u>1</u>	<u>1</u>	<u>0</u>	

ProblemNotes could not duplicate concern. install new trigger assm, clean action at no charge. F.L.S. 02/18/05

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date