

File Number:	19877		Arms Service number:	77178	
Last Name:	TOM MILLER GUNSMITHING		First Name:		
Street:	4607 OLIVE HWY., UNIT 3		City:	OROVILLE	
State:	CA	Zip:	95966	Home Ph:	
Work Ph:	530-589-5614	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	2/17/2004	Date Opened by P/S:	2/17/2004	Caliber:	3006
Date of Incident:		Date Closed:	2/17/2004	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	721	Serial:	238224	Date Code:	CYY
RAMAC:	721	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
				Obsolete:	<input checked="" type="checkbox"/>
Custody:		Comments:	No bolt with rifle - returned with firing pin assembly only. Unable to test for concern. The sear in the TA was coated with sticky residue and stuck to the sidewalls of the TA. Fit new bolt if possible (normal charges) or send for the rest of the bolt assembly and install new extractor and install new TA and clean action (\$20) under the bolt lock modification program.		
Time of Modification:	9:08:12 AM				
Date of Modification:	2/17/2004				