

Serial Number:

238224

Model: 721



RE00077178

TOM MILLER GUNSMITHING

4607 Olive Hwy., Unit 3
OROVILLE, CA 95966

INVOICE

1237

(530) 589-5614 FAX (530) 589-5602

TO Remington Arms Co.
14 Hoefler Avenue
Ilion, NY 13357

DATE 1-27-04	ORDER NO.
SHIP TO	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS
ATTN. Repair Dept.:				
Please replace trigger assembly. Goes off when you close the bolt.				
Replace the bolt. Does not extract.				
Thank You, Tom Miller				
77178				

Thank You!

NO Bolt with rifle - Fit new bolt if possible - normal charges
or send for rest of BA and install new extractor.Install new TA and clean action - Quote \$20 ~~for~~ ^{under} the Bolt
lock modification program

FCS 1/17/2004