



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00068680	Description/Serial Number A6359054	Repairman - Bruce Travis
Account # - R-	Model 700 Center Fire Caliber: 270 WIN	Date Received - 8/29/2003
	ADL	Estimate Date - 8/21/2003
		Current Date - 9/4/2003
Customer SAM TEGELER RT 1 BOX 2563 HOUSE NUMBER 1301 POUNDING MILL BRANCH RD POUNDING MILL. VA 24637 US		Return To SAM TEGELER RT 1 BOX 2563 HOUSE NUMBER 1301 POUNDING MILL BRANCH RD POUNDING MILL. VA 24637 US
Phone (H) (276)-963-3029	Fax	
Phone (W)	Email STEGLER@PMQC.COM	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION
M240	BOLT LOCK SAFETY MODIFICATION	M240	BOLT LOCK SAFETY MODIFICATION	M240	BOLT LOCK SAFETY MODIFICATION
M990	GUN FIRED WHILE ENGAGING SAFETY				

Material #		MaterialDesc		Repair		Quantity		Quantity		Quantity		Warranty	
						Needed		From Inv		From Kit		(Y/N)	
Part													
F26345		700 TRIG ASSB RH				1		1		0		Y	
Part Total:						1		1		0			
Service													
4000119		GR-TEST				1		1		0		Y	
4000104		ARMS SERV SHIPPING & HANDLING				0		0		0		Y	
4000116		GR-LABOR				20		20		0		N	
Service Total:						21		21		0			

Condition WOOD SLIGHTLY MARRED
ProblemNotes action and trigger assm dirty. clean action and replace trigger assm for \$20.00 quote

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date