

Arms Services Repair & Estimate System

File
Add Repair
Estimate Repair
Expedite Repair
Inquiry
Repair Tools
CSR Tools
Reports
Table Maintenance
System Maintenance
Help

CSR Notes Maintenance

Repair Nbr: RE00059667

High Priority

Serial: G6217731 Model 700 Center Fire Caliber:
308 PSS Less STOCK

Repairman: Richard Hilts
Status: Repairing 1/22/2003 9:26:28 AM

CSR Notes:

Comments To Repairman:
REPLACE TRIGGER ASSEM.
AT NO CHARGE!!!JSE
CUSTOMERS COMPLAINT
THAT GUN DISCHARGES
ACCIDENTALLY WHEN PULL

Repairmans Comments

Payment CSR:

Change Priority

History

Ship Hold

Update

Close

M114	NO CORRESPONDENCE
------	-------------------

Problems Found

Code	Desc
M123	FORWARD TO PRODUCT SE

forward to product
service for inspection

CSR Comments

YOU PULL THE TIGGER ON SAFETY AND
THAN WHEN YOU SWITCH TO FIRE IT
GOES OFF. PLEASE MAKE NEW TRIGGER
AS LIGHT AS POSSIBLE.

Repair Search

Refresh

Close

pencer 1/22/2003 11:13 AM CAPS NUM INS SCRL

PS06190