


February 27, 1995



The Remington Arms Company  
14 Hoefler Avenue  
Ilion, New York 13357

**RE: CUSTOMER NUMBER 114482**

Enclosed is my Remington 700BDL Serial Number B6855566. On three (3) separate occasions when the Safety Selector Switch has been moved from the safe position to the fire position the rifle has discharged on its own. I would appreciate you looking into this matter and letting me know what the problem is.

If you need any further assistance in this matter, please don't hesitate to contact me.

Very truly yours,  
**S. TOUB & ASSOCIATES, INC.**



Samuel G. Toub, P.E.  
President

SGT:btg

14215 Proton Road  
Dallas, Texas 75244  
214/386-5629 Fax: 214/386-7274