

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 95-09169

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
03/03/95	03/20/95	BO 1-77	A06398863		
ACCESSORIES W/STUDS					

FROM:

TUCKER, J O
345 HILLTOP
ELKHART

KS 67950

SHIP TO:

TUCKER, J O
345 HILLTOP
ELKHARTADL
Prod.
Sov.
KS
67950

CUST NO: 117211 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA UPS

CONDITION

NEW
LIGHTLY WORN
☒ WORN
VERY WORN
UNREPAIRABLE
MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

33.00
Total

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
TRIGGER GROUP	A1	B1				
TRIGGER GROUP		B2			E1	
TRIGGER GROUP		B3			E2	
TRIGGER GROUP		B4		D1	E3	F3
TRIGGER GROUP		B5		D2	E4	F4
TRIGGER GROUP			C1	D3	E5	F5
TRIGGER GROUP			C2			

IN FAULT: Mfgn 1/77 Gun fired as recd. after pulling trigger with safe on then releasing safe. Firing pin also follows down intermittently. Trigger overtravel screw missing and both pounds pull and sear engagement screws have been altered outside of factory. Exchange trig. assy at a special price strictly as a gesture of good will.

RTS

COMMENTS

Trig pull measured 3 to 3 1/4 lbs as recd.
Sear engagement measured .013
Stock glass bedded

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS06229