

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 95-16140

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
06/07/95

DATE OPENED
06/08/95

DATE CODE
CB 4-81

SERIAL NUMBER
A1735009

NEW SERIAL NUMBER

MODEL AND GRADE
552 22

BDL

ACCESSORIES

FROM:

TUCKER, L E
10077 HEBER SPRINGS RD
CONCORD AR 72523

SHIP TO:

TUCKER, L E
10077 HEBER SPRINGS RD
CONCORD AR 72523

CUST NO:121150 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

6-13-95 UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

[Signature]
6/13

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Shell head separation using Viper Ammo

MAIN FAULT

Star sent to product service for evaluation and recommendations recommended. Chamber is extremely dirty and a piece of brass was adhered to wall, headspace is excessive. Exchange barrel at N/C as a gesture of good will.

PARTS

BBL Assy

Disconnecter

COMMENTS

Suggest chamber and bore be cleaned more frequently

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS06233