

RECEIVING AND ESTIMATING REPORT

INITIAL FP3		CUSTOMER ORDER NO.		COMMENTS 64			
DATE RECEIVED 12/11/90	DATE OPENED 12/17/90	DATE CODE B0 1-77	SERIAL NUMBER A6408324	MODEL AND GRADE 700 30-06 BDL		ORDER R 90-32734	
ACCESSORIES W/STUDS							

FROM:

TOM'S HANDLOADING CENTER
45A WINN ST
BURLINGTON MA 01803

SHIP TO:

TOM'S HANDLOADING CENTER
45A WINN ST
BURLINGTON MA
01803

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED 1-9-91	VIA UPS
----------------	--------------------	---	------------	---------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☒ MARRED ^{wood over}

CUSTOMER'S REQUEST

inspect and repair - rifle discharged when the safety was put in the "On" position

MAIN FAULT

Cannot duplicate complaint, as by design a m/200 rifle cannot fire with the safety "on" since the firing pin is blocked.

Trigger and safety assembly operate properly - trigger pull 4 1/2 pounds; acc. left .008". No fault found.

PARTS

Offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of goodwill, if it is of better value to you.

REPAIRMAN 64	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV 7/90

PS06248