

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
EPS A11553							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE			ORDER
05/10/91	05/13/91	AQ 3-78	A6572255	700 7MM MAG BDL			R 91-10713
ACCESSORIES		SCOPE BASE		L/SIGHTS			
W/STUDS							

FROM: TROP GUN SHOP 709 CLOVERLEAF ROAD ELIZABETHTOWN PA 17022	SHIP TO: TROP GUN SHOP 709 CLOVERLEAF ROAD ELIZABETHTOWN PA 17022
---	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *Fires when closing bolt.*

MAIN FAULT: *Cannot duplicate complaint. For every trigger assembly has been completely mis-adjusted out of factory as evidenced by foreign bolt on adjustment screws - 1) screw engagement is extremely loose 2) over travel excessive. Firing pin spring is needed if heavily oiled. It has been triggered with and improperly maintained. See left .008" Trigger pull 3 1/2 pounds.*

Send quote for new trigger assembly at 1/2 normal cost as gesture of good will.

Note: under claims with is less than a year old, however, it was produced in March of 1978!!

HS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD66