

3-12-92

To: Arms Service Division

I am sending my Remington Model 700LH-BDL for service work. The safety lever seems to malfunctioning. Last November upon entering the woods of Vermont for my annual hunting trip I loaded the magazine and closed the bolt thus loading the chamber. When I moved the safety lever to the FIRE position the gun discharged without my finger being on the trigger. Luckily no one was hurt. After I ejected the empty cartridge and reloaded I moved the safety back and forth but it would not malfunction again that day. The following morning the exact same scenario occurred. I was using Remington 30-06 Springfield Factory Loads. I'm sure the folks at Remington Arms will not let a serious safety deviation like this go unrepaired. I'm not sure of the warranty situation with this firearm but I'm sure the craftsmen at Remington value their reputation and their dedicated customers.

Sincerely

D. D. Topham

Remington Model 700LH-BDL
serial B6723854

David Topham
31 Indian Trl
Hanson, Ma 02341
Home Phone 1-617-293-1301
Office 1-508-5808037