

Repair Order Number



Repair Order Number RE00065979	Description/Serial Number 6761291	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire Caliber: 30 06	Date Received - 6/5/2003
	LEFT HAND	Estimate Date - 6/4/2003
		Current Date - 6/9/2003
Customer JOHN UNDERWOOD 322 HEMLOCK AVE P.O. BOX 308 ROYAL CITY. WA 99357 US		Return To JOHN UNDERWOOD 322 HEMLOCK AVE P.O. BOX 308 ROYAL CITY. WA 99357 US
Phone (H) (509)-346-2592	Fax (509)-346-2040	
Phone (W)	Email drunder@bossig.com	

Reported		Problems	Found
M992	FIRES ON CLOSING SOMETIMES	M123	FORWARD TO PRODUCT SERVICE F
M993	WILL NOT ALWAYS COCK		

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F32895		700 TRIG ASSB LH	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116		GR-LABOR	20	20	0	N
4000118		GR-CLEAN	1	1	0	Y
4000119		GR-TEST	1	1	0	Y
Service Total:			22	22	0	

ProblemNotes	Parts working sluggish from being covered with a sticky substance. Poor maintenance. Replace trigger assembly \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date