

March 27, 1995

Remington Arms Co.
Product Service
14 Hoefler Avenue
Ilion, NY 13357
Attn: J. Kast

Dear Mr. Kast,

Enclosed please find, a trigger assembly which I removed from my Model 700 BDL. The problem with this trigger is that when I moved the safety to the fire position, the gun would occasionally fire. The first time this happened, I thought I had errored and accidentally pull the trigger when I released the safety. However, I was later able to duplicate the problem again without having my finger near the trigger.

I began to adjust the trigger to insure proper sear engagement, however, I then decided the resolution of this problem would best be left to Remington Arms.

Please repair or replace this trigger.

If you have any questions, I can be reached at:

Home - (810) 627-9297
Office - (810) 795-9709

Please send the new or repaired trigger assembly to:

Transpak Inc.
6515 Cobb Drive
Sterling Hts., MI 48312
Attn: Mitch Urbanski

Sincerely,

Mitch Urbanski
Mitch Urbanski

mpu394

PS06311