

Repair Order Number



Repair Order Number RE00073009	Description/Serial Number A6615736 REPLACEMENT G6324802	Repairman - Herb Brown
Account # - R-	Model 700 Center Fire Caliber: 30-06	Date Received - 11/20/2003
	SPRG ADL	Estimate Date - 11/17/2003
		Current Date - 12/10/2003
Customer US GEOLOGICAL SURVEY ROBERT OSCARSON MAIL STOP 919 345 MIDDLEFIELD ROAD MENLO PARK. CA 94025 US		Return To US GEOLOGICAL SURVEY ROBERT OSCARSON MAIL STOP 919 345 MIDDLEFIELD ROAD MENLO PARK. CA 94025 US
Phone (H) (650)-329-5117	Fax (650)-329-4732	
Phone (W)	Email roacarson@usgs.gov	

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M990	FIRING PIN FALLS WHEN SAFETY IS RELEASED		
M992	BOLT RETAINER MLFUNCTIONS		

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F26345	700	TRIG ASSB RH	1	1	0	N
F33455	700	BBL ASSB 30-06	1	1	0	N
F92897	700	BOLT ASSB BDL MAX LONG F1	1	1	0	Y
Part Total:			3	3	0	
Service						
4000104	ARMS SERV SHIPPING & HANDLING		0	0	0	N
4000117	GR-PROOF		1	1	0	Y
4000119	GR-TEST		1	1	0	N
4000294	GR-CHECK TPA		1	1	0	Y
Service Total:			3	3	0	

Condition	# ENGRAVED ON RECEIVER G-351278				
ProblemNotes	Bore heat checked. Excessive head space. Trigger covered with sticky substance. Spec. price trigger assm.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date