

~~REMINGTON ARMS.~~

I purchased the enclosed Remington
700 ADL 270 Cal Serial # C6260561
for hunting deer in Southwestern
Virginia. From the very beginning
I was unable to chamber Remington
factory ammunition without using
excessive force to close the
bolt. Winchester factory ammunition
does chamber so I switched to
their ammunition and hunted.
I have never been able to
group the gun at less than
4" at 100 yards however I
used the gun with limited success
being unable to bring down deer
at ranges exceeding 150 yards
due to the inaccuracy.

Hunting season 1993 brought
on a new problem, one that
is too dangerous for me to live

with - I had only 2 rounds
of Winchester ammunition with
me and used both to bring
down a Deer - The deer
needed a third shot to complete
the kill - With no Winchester
Ammo left I chambered a
Remington factory round - The
bolt would not close - I
applied force - the bolt
seated and the handle
started downward - the
rifle discharged -
I want like a replacement
rifle in like caliber to correct
this situation - I cannot
ever trust hunting with this
rifle after it discharged on
its own - You may contact
me at 703-755-4011 after 5 PM EST.
if you have any questions

DAVID CLANTZ, P.O. Box 81, LAMBERTVILLE, NJ 08523