

Robert J. Vande Walle  
2550 Parkwood Drive  
Green Bay, WI 54304

Remington Arms Company  
14 Hoefler Avenue  
Ilion, New York 13357

RE: Safety Modification  
Remington Model 700 ADL  
Caliber .30-06  
Serial Number 6515427

June 3, 2002

*Could not Duplicate  
TA settings altered.  
Install new TA, clean action under  
Bolt Lock modification program.  
FCS 6/14/02*

I am herewith sending you my Model 700 ADL for inclusion in your "safety modification program" per my telephone discussion with a customer service representative on May 28, 2002. Enclosed is my check number 2701 in the amount of \$20.00 for this service. While I have had at least two accidental firings while unloading the rifle over the past 29 years, I have really enjoyed this fine rifle.

Sincerely,

*R. Vande Walle*  
Robert J. Vande Walle  
(920) 498-9363 (Home)  
(920) 496-6715 (Work)  
Email: rvandewalle@new.rr.com

*22  
BW = 2/72*

