

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00046090	Description/Serial Number 6477653	Date Received - 5/9/2002
Account # - R-	Model 700 Center Fire Caliber: 7 MM	Estimate Date -
	MAG BDL	Current Date - 5/13/2002
Customer VALLEY POLICE SUPPLY 7719 HARFORD ROAD BALTIMORE. MD 21234 US		Return To VALLEY POLICE SUPPLY 7719 HARFORD ROAD BALTIMORE. MD 21234 US
Phone (H) (410)-668-2171		Fax (410)-668-6693
Phone (W)		Email celebshooter@aol.com

Problems			
Reported		Found	
M993	FIRE WHEN PLACED ON SAFE	M123	FORWARD TO PRODUCT SERVICE FO
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Action and trigger assm. covered with sticky substance. The trigger adjusting and stop screw have been re-set. Cleae action and replace the trigger assm. at spec. price \$ 20.00 .

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		23	

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357


10 LBS 1 OF 1

COD

SHIP

TO:

VALLEY POLICE SUPPLY
7719 HARFORD ROAD
BALTIMORE MD 21234




MD 211 9-40



UPS GROUND

TRACKING #: 1Z 114 813 72 1188 3269



BILLING: PREPAID
COD \$20.00

INV#: RE00046090

ASC 3.70 J69K/J64K 14.0 01/2002