

Repair Order Number



Repair Order Number

RE00084778

Description/Serial Number

E6769874

Repairman - Carl Cotton

Date Received - 9/14/2004

Account # - R-

Model 700 Center Fire Caliber: 3006  
BDL

Estimate Date -

Current Date - 9/21/2004

Customer

VAN RAYMOND OUTFITTERS  
388 S MAIN ST

Return To

VAN RAYMOND OUTFITTERS  
388 S MAIN ST

REWER. ME 04412 US

REWER. ME 04412 US

Phone (H) (207)-989-6001

Fax

Phone (W)

Email

Reported

M123 FORWARD TO PRODUCT SERVICE  
FOR INSPECTION  
M992 FIRED WHEN TAKEN OFF SAFE

M106 COULD NOT DUPLICATE CUSTOMER

Material # MaterialDesc

Quantity  
Needed

Quantity  
From Inv

Quantity  
From Kit

Warranty  
(Y/N)

Part

F26345 700 TRIG ASSB RH

Part Total:

1	1	0	Y
1	1	0	

Service

4000104 ARMS SERV SHIPPING & HANDLING

4000118 GR-CLEAN

4000119 GR-TEST

4000294 GR-CHECK TPA

Service Total:

0	0	0	Y
1	1	0	Y
1	1	0	Y
1	1	0	Y
3	3	0	

ProblemNotes

Trigger assy. and action had some sort of a heavy lubricant. Replacing trigger assy. and cleaning action at n/c.

Repairman	Proof	Clean	Test	Target	Pattern
Gallerly Tester	Date	Date	Date	Date	Date