

Remington Arms Co. Inc.
Arms Service Division
Ilion, N.Y. 13357

ORC
91-1

PA
5602


UPS

Jack Vrabel

2321 3rd Ave.

Altونا, Pa. 16602

Letter #1
m/722



Dear Sir:

I'm the proud owner of a 722 Rem. Serial # 249357 in .222 Cal. I bought the gun used about 5 yrs ago, and it's my favorite ground hog gun, on farms where noise can be a problem. The gun has never given me any trouble until recently. At the range, while sighting in, the rifle fired pre-maturely, lowering the bolt handle. I repeated the process, on an empty chamber several times with the same result. I would like to have this problem corrected by the factory if possible, because of the safety factor. Since I owned the rifle, the trigger mechanism has never been tampered with in any way. I have no idea who the previous owner was, or if they had any work done in this area. Please let me know if you can correct this problem, and give me an estimate on the cost of the repair. I'd feel alot

AL

MARRED

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

2.4

PATTERN

DATE

PS06358

safer if the work was done at the factory.
Hopefully you can help me in this matter,
because the gun is in beautiful shape con-
sidering when it was built, probably in the
1950's right? Let me know, either way on your
decision. Thanks

Sincerely
Rick Krabel

Mr
23
AL
8