

File Number:	21781		Arms Service number:	102187	
Last Name:	VANLANDINGHAM		First Name:	PAUL	
Street:	RR #1 BOX 589A		City:	MARTHA'S VINEYARD	
State:	MA	Zip:	02905	Home Ph:	508-696-7842
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	NAGLE	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	REPLACE TRIGGER ASSEMBLY \$20		Settlement Amount:	\$0.00	
Date Opened Rem:	10/14/2005	Date Opened by P/S:	11/7/2005	Caliber:	30 06
Date of Incident:		Date Closed:	11/7/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	6280906	Date Code:	
RAMAC:	700	Date Mfgd:	9/1/1969		
Litigation:	☐	PreLitigation:	☐	Obsolete:	☐
Custody:		Comments:	Trigger assembly contaminated with a sticky substance causing sear cam to stick to side plates. Replace TPA and clean action under the bolt lock program for \$20.00. Repair and Shipping Document 11/28/05.		
Time of Modification:	8:44:29 AM				
Date of Modification:	11/17/2005				