

Repair Order Number



Repair Order Number RE00102187	Description/Serial Number 6280906	Repairman - Herb Brown
Account # - R-	Model 700 Center Fire Caliber: 30 -06	Date Received - 10/25/2005
		Estimate Date - 10/14/2005
		Current Date - 10/31/2005
Customer PAUL VANLANDINGHAM RR1 BOX 589A VINEYARD HAVEN. MA 02568 US		Return To PAUL VANLANDINGHAM RR1 BOX 589A VINEYARD HAVEN. MA 02568 US
Phone (H) (508)-696-7842		Fax
Phone (W)		Email

<u>Reported</u>	<u>Problems</u>	<u>Found</u>
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123
M992	FIRES WHEN USING BOLT IF SAFETY IS NOT ON	FORWARD TO PRODUCT SERVICE F

<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	Trigger assm. contaminated with a sticky substance causing searcam to stick to side plates. Replace TPA. and clean action under bolt lock program for \$ 20.00.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date