

Remington Arms Co., Inc.
Product Service
Legal Case #:2142

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
141089	2/14/2008	2/15/2008	2/15/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Academy Sports	Academy Sports		710 Skyland Blvd	Tuscaloosa	AL	35405		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S rifle fires on its own C	Cause:4015 Improper Maintenance Concern:1025 Unexplained Discharge - No Mention of Safety Position		Unknown	

2/18/08-correspondence from repair-rifle will fire on its own whether the safety is on or not or if you dont even pull the trigger.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	7/300 SAUM	24791	7782578	XW	12/19/2002
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACADEMY CORP		U			

CONCERN:FIRES ON IT'S OWN

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	35	2/18/2008				

2/18/08-replace tpa at n/c.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/15/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	TRIG AND TRIG PIN RUSTED,TRIG BINDS WILL FOLLOW DOWN
	Description		22" 300 SAUM
	Date Code		XW
	Bore Plugged	False	

Barrel	Bulged	False	BOLT # DOES NOT MATCH SER#
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/7 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Like new; Not Functioning	TRIG AND PIN RUSTED
	Pull	---Select---	10+#
	Altered	False	
	Sub-Assembly	Other Remington	

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: RE00141089
Serial: 7782578 Model: 7 Center Fire Caliber: 300
REM SA ULTRA MAG Produced: 12/19/2002
Repairman:
Status: New 2/14/2008 12:45:54 PM

Verify Repair: High Priority

Address Information

Customer: ☒ Received From Return To: ☒ Received From

Name: ACADEMY SPORTS
Address 1: 710 SKYLAN BLVD
Address 2: PO Box:
City: TUSCALOOSA
State: AL Zip Code: 35405 Country: US
State: AL Zip Code: 35405 Country: US

FFL: ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Desc1	Current Status
1/23/2008 2:38:4	New	valentids	Repair Added	New
2/2/2008 12:45	Update	valentids	Repair information change	2/14/2008 12:45:54 PM
2/14/2008 12:45	Expedite	valentids	From Check In	valentids
2/15/2008 8:08:4	Comment	supryfl	Returned to AS for repair	Product Services
				Repair Location
				ILN
				Current Location
				ILN
				Transfer Number

☐ Shipping Hold
☐ Interface Hold
☐ Estimate Sent
☐ Parts Received
☐ Passed Inspection
☐ Return As Received
☐ Has been Approved
☐ Internal Repair

Repair Search Refresh Close

supryfl 2/15/2008 8:09 AM CAPS NUM INS SCPL

start © 2008 Microsoft Outlook Remington-Union Arms Company Current Cases - Microsoft Arms Services Repair 8:09 AM

2142

To Whom It May Concern:

The enclosed firearm is being returned for repair: Serial # 7782578. The rifle will fire on its own whether the safety is on or not or if you don't even pull the trigger..

xw12/02
107#
010
22"

Thanks,
Chris Carter
Academy Sports and Outdoors 160
710 Skyland Blvd.
Tuscaloosa, AL 35405

Guns owner: Academy 160

TRIG. + TRIG. PIN RUSTED CAUSING
TRIG. TO BIND. REPLACE TPA,
check over, clean AT N/C
#230145

Serial
Number:

7782578

Model: 7



RE00141089

(BOLT + SER # DO NOT MATCH)