Remington Arms Co., Inc.
Product Service
Legal Case #:2133

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 140932 2/12/2008 2/13/2008 2/13/2008

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact
PO Box 442

Reporter Michael Donovan 6 Rambler Rd Lincolndale NY 10540 H 914-248-4613

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4014 Defective Parts
Unknown

S fires when bolt is closed Concern: 1008 Fired on Bolt Closing

C

2/15/08-correspondence from repair-shells were not ejecting, now the gun goes off when bolt is closed.lw

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 7/223 REM
 24745
 S7639595
 AU
 3/25/2000 7:02:15 PM

Date Purchased Where Purchased Accessories Original Owner

DAVIS SPORT SHOP INC U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/7/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Replace TA at

n/c

Repair/Replacement
Cost
Bate
35
Repair/Replacement
Date
2/15/2008

2/15/08-replace ta at n/c.lw


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
<u> </u>	Examiner		B.TRAVIS
	Exam Date		2/13/2008
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4079	Other - Unexamined	
	Description		20" 223 REM
	Date Code		AU
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2133&Type=Case

2/18/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/7 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Like new; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
T-:	Pull	Select	1.5#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	



2-15

re you the original owner?: YES NO lame: Michael Donovan Da ddress (no PO Boxes): P.O Box 442	te of Purchase: 6 Ramble Rd ate: N. 7 Zip: 10540 x:
re you the original owner?: VES NO lame: Michael Donovan Da ddress (no PO Boxes): P. O Box 442 / ity: Liñco Inlule St. hone (Daytime): (914) 248 - 4613 Fa. -mail Address: I would like to receive future e-mail updates from Rem lease describe your problem: Ormal were not lacetting a coes of a sen Please Check H	te of Purchase: 6 Ramble Rd ate: N 7 Zip: 10540 x:
ddress (no PO Boxes): P. O BON 449 ity: Linco Inlule St hone (Daytime): (914) 248 - 4613 Fa -mail Address: I would like to receive future e-mail updates from Rem lease describe your problem: Ormal were not eachting goes off when Plane Geolo H	G Rambler Rd ate: N. 7 Zip: 10540 x: ngton.
ity: Linco Inlule St. hone (Daytime): (914) 248 - 4613 Famail Address: I would like to receive future e-mail updates from Rem lease describe your problem: Ormal were not exceptive goes of misen Plane Geolo Ha	zip: 10540 x:
hone (Daytime): (414) 248 - 4613 Fa -mail Address: I would like to receive future e-mail updates from Rem lease describe your problem: Were not least to see for the following of the followi	ngton.
hone (Daytime): (414) 248 - 4613 Fa -mail Address: I would like to receive future e-mail updates from Rem lease describe your problem: Were not least to see for the following of the followi	ngton.
I would like to receive future e-mail updates from Rem lease describe your problem: Orms f were not eachtrize coes off usen Please check the	
were not excerting of content of the character of the	problem vas shells Now the gen bolt is closel.
please check th	bott in closel.
please check th	bolt is closel.
Please check th	P. Louise Du de
	the first of the second
/	very daneous.
and the second s	thadlo-
e de la companya del companya de la companya del companya de la co	m. W. Laar
mmunition Information:	
	pe;
Other (i.e. bullet weight/type, shot size, powder):	
landload Information:	
	wder Weight:
	mer Used:
iullet Type/Shot Size:	loader Used:
irearms Care (Cleaning and Lubrication):	
rand of cleaning solution used:	
OL	nds)
	ounds)
77745 -	imber of rounds)
,	3. 10dilda)