

Remington Arms Co., Inc.
Product Service
Legal Case #:2140

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
141634	2/13/2008	2/14/2008	2/14/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bass Pro	Bass Pro		7970 East 49th Ave	Denver	CO	80238		W 720-385-3674

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fired when it was taken off safety	Concern:1007 Fired on Safe Release		Unknown
C				

2/15/08-correspondence from repair-gun fired when it was taken off safety.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	A6645953	DQ	9/20/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	OUTDOOR SPT DAYTON OH	TWO PIECE SCOPE BASE,BBL NOT OF REM MFG	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
	Repair/Replacement Cost	Repair/Replacement Date				

2/15/08-quote sent to replace TA under SMP.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/14/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 3006 NOT OF REM MFG
	Date Code		
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.009
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE,BBL NOT OF REM MFG

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00141634** Serial: A6645953 Model: 700 Center Fire Caliber: Repairman: Patrick Bielanski
 30.06 Produced: 09/20/1978 Status: Repairing 2/14/2008 8:31:41 AM

Verify Repair: ☐

Address Information

Customer: ☐ Received From: ☒ Return To: ☐ Received From: ☐

Name: **BASS PRO SHOPS** **BASS PRO SHOPS**

Address 1: **7970 EAST 49TH AVENUE** **7970 EAST 49TH AVENUE**

Address 2: PO Box:

City: **DENVER** **DENVER**

State: **CO** Zip Code: **80238** Country: **US** State: **CO** Zip Code: **80238** Country: **US**

FFL: ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date:	Code	User ID	Desc1	Current Status
2/13/2008 10:11	New	sanguinegl	Repair Added	Repairing
2/13/2008 10:14	Closed	sanguinegl	Closed at Expedite	2/14/2008 8:31:41 AM
2/14/2008 7:40:1	ReOpened	pencerl		bielanskpp
2/14/2008 7:40:2	Expedite	pencerl	From: Product Services	Repair Bench:
2/14/2008 8:31:4	Estimate	bielanskpp	Estimate Update	Repair Location:
2/14/2008 8:33:2	Estimate	bielanskpp	Estimate Update	ILN
				Current Location:
				ILN
				Transfer Number:

☐ Shipping Hold
☐ InterFace Hold
☐ Estimate Sent
☐ Parts Received
☐ Passed Inspection
☐ Return As Received
☐ Has been Approved
☐ Internal Repair

Repair Search **Refresh** **Close**

supryll 2/14/2008 9:27 AM CAPS NUM INS SRL

start | Microsoft Outlook | Arms Services Repair | Microsoft Excel | Port Security Watch | 9:27 AM

Belt lock mod. R. action program repair
 not being test fired due to non-Remington
 barrel on rifle. will be bench tested
 and final tested at Arms Service.

2140

Customer stated that gun fired when it was taken off safety. Please contact Robert Longone, service writer/gunsmith for payment. (720)385-3674.

.009
DQ 9/78
24" Not Rem.
2.5#

Serial Number: **A6645953**

Model: **700**



RE00141634

Bbl. not of rem. mfg.
could not duplicate concern
mfg-set screws altered.
Replace TPA, check over, clean
under BOLT LOCK program.
Con \$20.00 + S+H.

(DO NOT TEST)

ORIGIN ID: BKFA (720)385-3600 Mike Wilkins Bass Pro Main Office 7970 East 49th Avenue Denver, CO 80238 UNITED STATES US		Ship Date: 05FEB08 ActWgt: 8 LB System#: 1382491/INET8011 Account: S *****	
Remington Arms Co. Att: Arms Service 800-243-9700			
14 HOEFLER AVE		FedEx Express	
ILION, NY 133571816			
Ref: 02562110006533001 INV: PD: 328322 1-30-08 Dept:		CL5120707/22/24	
		Delivery Address Barcode	
		BILL SENDER	
TRK# 7920 0039 7847 0201		THU - 07FEB ** 2DAY ** DSR	
AA		133571816 NY-US SYR	
SG UCAA			

Part # 156297-435 RIT 08/07