

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2459

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 146238 | 6/10/2008   | 6/11/2008       | 6/11/2008   |               |         |     |          |

## Customer Information

| Type     | Business                     | First Name | Last Name | Street          | City   | State | Zip   | Age | Contact        |
|----------|------------------------------|------------|-----------|-----------------|--------|-------|-------|-----|----------------|
| Reporter | Capital Sports & Westernwear | Al         | Charrat   | 1092 Helena Ave | Helena | MT    | 59601 |     | W 406-443-2978 |

## Incident Information

| Claims | Codes                                                    | Repair Est. | Medical Treatment | Medical Status |
|--------|----------------------------------------------------------|-------------|-------------------|----------------|
| PI     |                                                          |             |                   |                |
| PD     | Cause:4006 Altered Adjustments or Components             |             | Unknown           |                |
| S      | fired on bolt closing Concern:1008 Fired on Bolt Closing |             |                   |                |
| C      |                                                          |             |                   |                |

6/13/08-correspondence from repair-fired on bolt closing and also when safety was moved from safe to fire.lw

## Firearm Information

| Mfg.           | Type                        | Model/Ga.            | SKU            | Serial   | Bbl. | DOM      |
|----------------|-----------------------------|----------------------|----------------|----------|------|----------|
| Remington      | CF/BA                       | 700/3006 SPR         | 20000          | B6418548 | AD   | 3/1/1983 |
| Date Purchased | Where Purchased             | Accessories          | Original Owner |          |      |          |
|                | G & G WHLSE DOUGLASVILLE GA | TWO PIECE SCOPE BASE | U              |          |      |          |

CONCERN:FSR,FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

| Settlement         | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|--------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Repair at discount |                         |                         |               |                 |                |               |
|                    | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |

6/13/08-quote sent to repair at discount. 1/2 normal charges. Altered set screws.lw

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                              | Comment      |
|-------------|--------------|-----------------------------------|--------------|
| Examination | Examiner     |                                   | B.TRAVIS     |
|             | Exam Date    |                                   | 6/11/2008    |
|             | Product Type |                                   | RF           |
|             | Action Type  |                                   | A            |
|             | Assigned To  |                                   | F.SUPRY      |
| Cause       | 4006         | Altered Adjustments or Components |              |
| Barrel      | Description  |                                   | 22" 3006 SPR |
|             | Date Code    |                                   | AD           |
|             | Bore Plugged | False                             |              |
|             | Bulged       | False                             |              |
|             | Fired        | False                             |              |

|                          |                        |                            |                                 |
|--------------------------|------------------------|----------------------------|---------------------------------|
|                          | Fired while Obstructed |                            |                                 |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning |                                 |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning |                                 |
|                          | Shroud                 | Slightly Worn; Functioning |                                 |
|                          | Face                   | Slightly Worn; Functioning |                                 |
|                          | Handle                 | Slightly Worn; Functioning |                                 |
|                          | Stop                   | Slightly Worn; Functioning |                                 |
| Extractor                | Condition              | Slightly Worn; Functioning |                                 |
|                          | Cut Condition          | Slightly Worn; Functioning |                                 |
|                          | Ext/Eject Test         | False                      |                                 |
| Locking                  | Block Condition        | ---Select---               |                                 |
|                          | Lug Condition          | Slightly Worn; Functioning |                                 |
|                          | Notch Condition        | ---Select---               |                                 |
| Overall                  | Exterior Condition     | Slightly Worn; Functioning |                                 |
|                          | Stock Condition        | Slightly Worn; Functioning |                                 |
|                          | Fore End Condition     | ---Select---               |                                 |
| Receiver                 | Condition              | Slightly Worn; Functioning |                                 |
|                          | Bulged                 | False                      |                                 |
| Safety                   | Description            |                            | STANDARD M/700 SAFETY           |
|                          | Function               | Like new; Functioning      |                                 |
|                          | Sub-Assembly           | Non-ISS                    |                                 |
| Sear                     | Lift                   | ---Select---               | .012                            |
|                          | Notch                  | Like new; Functioning      |                                 |
|                          | Tests                  | Test Fired                 | False                           |
| Feeding Test             |                        | False                      |                                 |
| Trigger                  | Condition              | Slightly Worn; Functioning |                                 |
|                          | Pull                   | ---Select---               | 3#                              |
|                          | Altered                | True                       | SET SCREWS ALTERED FOLLOWS DOWN |
|                          | Sub-Assembly           | M/700 Non-Bolt Lock        |                                 |
| Non-Remington Components | Description            |                            | TWO PIECE SCOPE BASE            |

**Arms Services Repair & Estimate System**

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

**Repair Inquiry**

Repair Number: **RE00146238** Serial: 86418548 Model: 700 LH Center Fire Caliber: 3006 SPRG Produced: 03/21/1983 Repairman: Status: New 6/10/2008 6:39:55 AM

Verify Repair

**Address Information**

Customer: Received From: Return To: Received From:

Name: **CAPITAL SPORTS WESTERN** **CAPITAL SPORTS WESTERN**

Address 1: **1092 HELENA AVE** **1092 HELENA AVE**

Address 2: **PO Box** **PO Box**

City: **HELENA** **HELENA**

State: **MT** Zip Code: **59601** Country: **US** State: **MT** Zip Code: **59601** Country: **US**

FEL

**Contact / Condition** **Problems** **Estimate** **History / Status** **Shipping / Billing**

| Date             | Code     | User ID  | Desc1                     | Desc2            |
|------------------|----------|----------|---------------------------|------------------|
| 6/10/2008 5:57:0 | New      | valentds | Repair Added              |                  |
| 6/10/2008 6:02:3 | Update   | valentds | Repair information change |                  |
| 6/10/2008 6:05:1 | Update   | valentds | Repair information change |                  |
| 6/10/2008 6:06:0 | Expedite | valentds | From: Check In            | To:              |
| 6/10/2008 6:39:5 | Update   | valentds | Repair information change |                  |
| 6/11/2008 7:40:1 | Expedite | pencerl  | From: Check In            | To: Repair Bench |

☐ Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair

**Current Status**

New

6/10/2008 6:39:55 AM

valentds

**Repair Bench**

Repair Location

ILN

**Current Location**

ILN

**Transfer Number**

Repair Search Refresh Close

supryll 6/11/2008 9:59 AM CAPS NUM JMS SCRL

start Inboxes Microsoft Out Microsoft Powerpoint Microsoft Excel Arms Services Repair

Repairman to Quote repair at  $\frac{1}{2}$  normal charges  
altered adjustments.

# MEMO LETTER

## CAPITAL SPORTS & WESTERN & ALL SEASONS SPORT SHOP

1092 HELENA AVENUE  
HELENA, MONTANA 59601  
PHONE (406) 443-2978 FAX (406) 442-8136

2459

34  
22  
AD 3/53  
012

TO  
Remington Arms  
14 Hoefler Ave.  
ILION N.Y. 13357

DATE 5-28-08 L.H.  
SUBJECT 700 BDL 30-06  
B6418548  
WEAVER BASES

DEAR SIRS.

OUR CUSTOMER SAYS THIS RIFLE HAS FIRED ON  
BOLT CLOSING AND ALSO WHEN SAFETY WAS MOVED FROM  
'SAFE' TO 'FIRE'

FIRING ASSM SET SCREWS ALTERED  
WILL FOLLOW DOWN. replace TPA,  
checkover, clean AT 1/2 NORMAN

PLEASE CHECK AND ADVISE.

COST - Quote

THANKS

Number: B6418548

Model: 700



RE00146238

SIGNED

AL Charvat