

Remington Arms Co., Inc.
Product Service
Legal Case #:2850

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 154647 | 11/5/2008 | 11/6/2008 | 11/6/2008 | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|---------------|------------|---------------|-------------|----------------|-------|-------|-----|----------------|
| Reporter | Kell Brothers | | Kell Brothers | 4539 Rt 209 | Elizabethville | PA | 17023 | | W 717-362-3234 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|--|-------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4006 Altered Adjustments or Components | | Unknown | |
| S | Fired on bolt closing Concern:1008 Fired on Bolt Closing | | | |
| C | | | | |

Customer says, discharge when closing bolt.

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|--------------------|----------------------|----------------|---------|------|----------|
| Remington | CF/BA | 700/222 REM | 20000 | 6267899 | BT | 1/1/1970 |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | ART COOK LAUREL MD | TWO PIECE SCOPE BASE | U | | | |

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| | | | | | | |

BLM Program

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 65.00 | 11/6/2008 |

Trigger screw settings altered, has very little trigger return, as received will follow-down as bolt is closed. Install new TA, clean action, and check over completely under the bolt lock modification program fls.

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|------------------------|-----------------------------------|-------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 11/6/2008 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | F.SUPRY |
| Cause | 4006 | Altered Adjustments or Components | |
| Barrel | Description | | 24" 222 REM |
| | Date Code | | BT |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |

| | | | |
|--------------------------|--------------------|----------------------------|---------------------------------|
| Bolt | Face | Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | --Select-- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | --Select-- | |
| Overall | Exterior Condition | Slightly Worn; Functioning | |
| | Stock Condition | Slightly Worn; Functioning | MARS/SCRATCHES |
| | Fore End Condition | --Select-- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | STANDARD M/700 BOLT LOCK SAFETY |
| | Function | Like new; Functioning | |
| Sear | Lift | --Select-- | .008 |
| | Notch | Slightly Worn; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | | False | |
| Trigger | Condition | Slightly Worn; Functioning | |
| | Pull | --Select-- | 2# |
| | Altered | True | SET SCREWS ALTERED |
| | Sub-Assembly | M/700 Bolt Lock | |
| Non-Remington Components | Description | | TWO PIECE SCOPE BASE |

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00154647** Serial: 6267899 Model: 700 Center Fire Caliber: Repairman: Status: New 11/5/2008 8:36:01 AM
 Verify Repair 222 REM Produced: 03/13/1970

Address Information

Customer Received From Return To Received From
 Name: **KELL BROTHERS** **KELL BROTHERS**
 Address 1: **4539 RT 209** **4539 RT 209**
 Address 2: **PO Box** **PO Box**
 City: **ELIZABETHVILLE** **ELIZABETHVILLE**
 State: **PA** Zip Code: **17023** Country: **US** State: **PA** Zip Code: **17023** Country: **US**

FFL: **8 23 043 01 98 58693 022009**

| Contact / Condition | Problems | Estimate | History / Status | Shipping / Billing |
|---------------------|-----------|---------------------------|--------------------------------|----------------------|
| Date | User ID | Desc1 | Desc2 | Current Status |
| 11/5/2008 8:27:1 | valentids | Repair Added | | New |
| 11/5/2008 8:35:2 | valentids | Repair information change | | 11/5/2008 8:36:01 AM |
| 11/5/2008 8:36:0 | valentids | Repair information change | | valentids |
| 11/5/2008 8:36:3 | valentids | From: Check In | To: | Product Services |
| 11/6/2008 9:51:4 | supryll | Returned for repair | Bolt Lock Modification Program | Repair Location |
| | | | | ILN |
| | | | | Current Location |
| | | | | ILN |
| | | | | Transfer Number |

Repair Search **Refresh** **Close**

View R

supryll 11/6/2008 9:52 AM CAPS NUM INS SCRL

start Inbox - Microsoft Out... Arms Services Repair... Microsoft Excel - PS H... Current Cases - Micro... 9:52 AM

Altered adjustments
 Bolt Lock Modification Program.

IST 1/70
24"
~~24~~
:008

Remington.

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

| | | | |
|---|--|-------------------------|------------|
| Model Number: 700 RDL | | Serial Number: 626 7899 | |
| Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | | DEALER | |
| Name: KEE BROWDER GUNN | | Date of Purchase: | |
| Address (no PO Boxes): 4539 RT204 | | | |
| City: ELIZABETH NJ | | State: NJ | Zip: 07023 |
| Phone (Daytime): 773 362 3234 | | Fax: | |
| E-mail Address: | | | |
| <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington. | | | |
| Please describe your problem: DISCHARGES WITH NO CYCLE | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Ammunition Information: REM | | | |
| Manufacturer: | | Type: | |
| Other (i.e. bullet weight/type, shot size, powder): | | | |
| | | | |
| Handload Information: | | | |
| Powder Used: | | Powder Weight: | |
| Case/Hull Used: | | Primer Used: | |
| Bullet Type/Shot Size: | | Reloader Used: | |
| | | | |
| Firearms Care (Cleaning and Lubrication): | | | |
| Brand of cleaning solution used: HOPKINS | | | |
| How often do you clean the bore? (Months or Number of rounds) | | | |
| How often do you clean the action? (Months or Number of rounds) | | | |
| Number of rounds) | | | |

Serial Number:

6267899

Model: 700



RE00154647

TRIG. SET screws altered, HAS
 mid TRIG. return, will follow down.
 replace TPA checkover check
 under bolt lock program for
 \$ 20.00 ± SKH.